




Explanation

- Existing Monitoring Wells
- Existing Piezometers
- Existing Boreholes
- Leviathan Creek Basin Landslide
- Creek
- Study Area
- Pit Underdrain Features
- Adit
- Road

Notes:
1. Other features based on Brown & Caldwell (1983), Herbst and Schiaccia (1982), and aerial photography dated October 22, 2009 (Atlantic Richfield, 2009e).
2. Survey monument SM-7 may not be installed if monument SM-32 is found in good condition and can be re-established for monthly surveys.



BOREHOLE, MONITORING WELL, AND PIEZOMETER LOCATIONS Leviathan Mine Site Alpine County, California		
Date: 05/17/2017	Project No. 0013091	
Figure 1		